


Leo Greiner
DRAFT

Bonding diagram for the Ultimate sensor cable - 2 power version
07/31/2012 updated 02/19/2013



change log:
2/19/2013 - remove bonds from pads 131, 132 for POR