

BOARD JUMPERED TO GIVE SHOWN CONFIGURATION  
 PIN NUMBERS ARE AS PER BONDING DIAGRAM AND NOT PHASE-1 DOCUMENTATION  
 THIS MODIFICATION FIXES THE BONDING DIAGRAM FLAW

